SOP 9 - Exiting Laboratory Environments

- A. Wash areas of exposed skin before leaving the laboratory.
- B. Leave contaminated gloves and other articles of protective clothing in the laboratory prior to exiting.

C. Verify that you and other laboratory personnel understand emergency exiting procedures, routes, and gathering points.

Page 1 of 1 Revision Date 1/18/2006